




FTSCLANT

2M/MTR



FTSCLANT 2M/MTR WEBSITE

www.ftsclant.navy.mil

Select "Command Programs"

Then Select "2M"



FTSCLANT SERVICES

- Total Commands: 172
- Site Certifications: 71
 - - Afloat 50
 - - Shore 21
- Technician Recerts 164
 - - Mini 75
 - - Micro 89
 - - Requiring Remedial Training 35 %
- Huntron 2000 Students 27


PROBLEM AREAS

- Commands lack a cohesive Command wide Progressive Repair Program.
- Personnel are not familiar with governing instructions.
- Commands do not possess the right mix of technicians to meet their configuration requirements.
- Technicians are not familiar with the MTRTS system.
- Lack of piece parts or technicians do not know how to obtain piece parts.
- Difficulty in ordering 2M tools and materials.

FY 2003 OUTLOOK

- Continue to deploy new equipment
- Certification Plan Modifications
- Focus on the Progressive Repair Process

PROGRESSIVE REPAIR



BEFORE	AFTER	BEFORE	AFTER
#Jobs	#Jobs	\$\$ K	\$\$ K
126.5	181	483.9	606.6
% Change	43.1%	% Change	25.3%